



# Technical Service Information

## ZF 5HP-24

### SLIPPING OR NO FORWARD ENGAGEMENT

**COMPLAINT:** Vehicles equipped with the ZF 5HP-24 transmission may exhibit a Slipping or no Forward engagement.

**CAUSE:** The cause may be, a broken snap ring groove in the "A" Clutch Drum allowing the "A" Clutch to slip, as shown in Figure 1.

**CORRECTION:** Replace the "A" Clutch Drum with the updated drum available from ZF.

**SERVICE INFORMATION:**

A CLUTCH DRUM (ZF part number).....1058 270 036




Figure 1