



Technical Service Information

4T80E

SLIPS IN FOURTH OR NO FOURTH

COMPLAINT: The transmission may slip in fourth gear or have no fourth gear. The "Service Engine Soon" lamp may illuminate with DTC P0734, gear ratio error in fourth, stored.
The affected vehicles are the 2000 Cadillac DeVille, Eldorado and Seville as well as the 2001 Oldsmobile Aurora.

CAUSE: This complaint may be caused by a warped lower control valve body channel plate, shown in Figure 1.
The warped channel plate causes a loss of fourth band apply pressure resulting in damage to the fourth band and the reverse clutch housing.

CORRECTION: Inspect the fourth band and the reverse clutch housing and replace them if necessary. Replace the lower control valve body channel plate, spacer plate and gasket.

SERVICE INFORMATION:

Lower Control Valve Body Channel Plate.....24200434
Spacer Plate And Gasket.....24213957
Fourth Band.....8684246
Reverse Clutch Housing.....24212654

Factory TSB.....01-07-30-005A

Special thank you to Stuart Nethery at Richmond Hill Transmission in Richmond Hill, Ga. for sharing his experiences with us.

4T80E

SLIPS IN FOURTH OR NO FOURTH




Figure 1