



Technical Service Information

ZF6HP26

TRANSMISSION FLUID LEAK

COMPLAINT: The transmission appears to be leaking from the pan gasket, (Refer to Figure 1).

CAUSE: The Mechatronic Sealing Sleeve o-rings (Refer to Figure 2) is leaking and running down along the pan rail giving the appearance that the pan gasket is leaking.

CORRECTION: Replace the Mechatronic Sealing Sleeve.

SERVICE INFORMATION:

Mechatronic Sealing Sleeve.....ZF Part Number 0501212190
Oil Pan/Filter Assembly For Manual Valve Body.....ZF Part Number 0501215789

ZF6HP26 TRANSMISSION FLUID LEAK




Figure 1




Figure 2