



Technical Service Information

DODGE/JEEP RE SERIES TRANSMISSIONS FORWARD CLUTCH FAILURE

COMPLAINT: Pre-mature failure of the forward clutch.

CAUSE:

1. Manual valve alignment is critical as the forward clutch is fed directly from the valve as seen in figure 1. If the manual valve becomes mis-positioned, pressure to the clutch drops as it dumps to an exhaust through the neutral circuit. There are two areas of wear that takes place in the valve body that causes the manual valve to be mis-positioned
 - a. The detent ball wears into the valve body due to the continuous movement and vibration of the manual valve linkage (Figure 2).
 - b. Wear also occurs where the detent lever pilots into the casting of the valve body. This too mis-positions the manual valve (Figure 2).
2. The stator support bushing (# 77 in Figure 3) is critical for proper support of the Input Shaft, particularly for the proper sealing of the green plastic style rings now being used in all the RE units (Figure 3). Poor support will compromise the ring's pressure retention causing the forward clutches to burn.
3. The forward clutch piston inner lip seal (# 108 in Figure 4) is known to shrink or deteriorate causing a loss of pressure.
4. Modified power programmers/performance chips designed to increase engine torque have been known to loosen the input shaft splines to the drum causing a loss of forward clutch pressure between these pieces.
5. Excessive end play clearance allowing the forward clutch drum to move too far forward causing sealing ring # 102 in figure 3 to move far enough out of the pump to produce a leak in the forward clutch circuit.

CORRECTION:

1. There are aftermarket sources which provide repair kits that correct the wear conditions related to the detent lever restoring the integrity of manual valve alignment. Otherwise, replace the valve body with one that does not have wear in the locations mentioned.
2. Replace the stator bushing.
3. There are aftermarket sources that provide modified inner lip seals for increased durability and pressure retention. Be sure to properly prepare the seal's surface area with 600 grit wet/dry paper.
4. Replace the forward drum assembly. If the power program/performance chip is kept in place, there are companies that provide modified performance parts designed to withstand the increased torque. The shaft and hub (# 104 in Figure 4) are usually billet in design or hardened 1 piece design.
5. Adjust end play according to manufacturer's procedures and specifications.

SERVICE INFORMATION:


Transtar sells steel rings for the turbine shaft in both small and large diameters.

Large diameter rings.....22177E

Smaller diameter rings.....22177A

DODGE/JEEP RE SERIES TRANSMISSIONS FORWARD CLUTCH FAILURE

TYPICAL 46RE/47RE PARTIAL HYDRAULIC SCHEMATIC "DRIVE" POSITION 3rd GEAR WITH TCC "ON"



Copyright © 2014 ATSG

Figure 1

DODGE/JEEP RE SERIES TRANSMISSIONS FORWARD CLUTCH FAILURE





Figure 2

DODGE/JEEP RE SERIES TRANSMISSIONS FORWARD CLUTCH FAILURE



DODGE/JEEP RE SERIES TRANSMISSIONS FORWARD CLUTCH FAILURE




Figure 4