



Technical Service Information

FORD 5R110W FLUID OUT THE VENT


COMPLAINT: A Ford truck equipped with a 5R110W transmission has a complaint of transmission fluid forced out of the vent. This an after overhaul condition.

CAUSE: Some transmission overhaul kits may contain pump assembly to case gaskets that have been incorrectly cut, Refer to Figure 1. The pump passage identification shown in Figure 2 illustrates how the improperly fitting pump gaskets cause fluid to leak out of the transmission vent.

CORRECTION: Be sure to place the pump gasket on the pump and case surface to insure the gasket aligns properly.

Many thanks to Max at King Transmission for sharing his experience with ATSG that made this bulletin possible.

**FORD 5R110W
FLUID OUT THE VENT**



Copyright © 2016 ATSG

Figure 1

**FORD 5R110W
FLUID OUT THE VENT**




Figure 2