

FORD CAST IRON FMX

2-3 FLARED SHIFT

After overhaul an FMX transmission may have a 2-3 flared shift. The main valve body spacer plate has a small hole over the 2-3 orifice check ball as seen in figure 1. Drill this hole out to 1/8".




Figure 1