



Technical Service Information

HONDA CR-V LIGHT THROTTLE VIBRATION

COMPLAINT: A 2012 to 2014 Honda CR-V may have complaints of a surge, shudder or vibration while driving under light throttle.

CAUSE: Software part number 37820-R5A-305 is faulty.

CORRECTION: Update automatic transmission software and change the transmission fluid using DW-1 fluid. Fluid capacities are 2.2 Liters (2.3 Qts.) for the 2 Wheel Drive models and 2.6 Liters (2.7 Qts.) for the All Wheel Drive models. Torque drain plug to 49 N~m (36 lb. ft.).

SERVICE INFORMATION:

Use the chart below in figure 1 to determine the correct updated software version.

YEAR/MODEL	PROGRAM IDENTIFICATION (or later)	PROGRAM PART NUMBER (or later)
2012 AWD	5A3160	37805-R5A-3160
2012 2WD	5AA250	37805-R5A-A250
2013 AWD	5AA150	37805-R5A-A150
2013 2WD	5AA050	37805-R5A-A050
2014 AWD	5AA350	37805-R5A-A350
2014 2WD	5AA250	37805-R5A-A250

Figure 1