

## FORD F150

### RATTLING SOUND FROM BELLHOUSING AREA

**COMPLAINT:** Some 2018 to 2019 Ford F150 Trucks built on or before February 12, 2019 with 5.0 Liter Engine may exhibit a rattling noise coming from the bellhousing area whenever the engine is running.

**CAUSE:** The torque converter studs are making contact with the engine to transmission metal spacer plate.

**CORRECTION:** Replace the engine to transmission spacer plate with a new spacer plate that has a bend for additional clearance as seen in figure 1.

**SERVICE INFORMATION:**

*New engine to transmission spacer plate.....JL3Z-7007-A*



Figure 1