



Technical Service Information

FORD 8F35

NO OR INTERMITTENT LOSS OF REVERSE

COMPLAINT: A 2019 to 2020 Ford or Lincoln equipped with the 6F35 transmission (see list below for the affected vehicles) may exhibit a no or intermittent reverse engagement. The MIL will be illuminated and trouble code P0766 "Shift Solenoid D Stuck Off".

CAUSE: A piece of debris has become lodged in the Solenoid D spacer plate orifice as seen in figure 1.

CORRECTION: Remove and disassemble the valve body and clean out the stuck piece of debris as seen in figure 2.

Vehicles covered under this bulletin:

2019 - 2020 Ford Edge
2020 Ford Escape
2019-2020 Ford Transit Connect
2020 Lincoln Corsair
2019 - 2020 Lincoln Nautilus

SERVICE INFORMATION:

Main Control Valve Body Cover Gasket.....JM5Z-7F396-A
Main Control Valve Body To Case Tube.....JM5Z-7G199-A
Motorcraft® Mercon® ULV Transmission Fluid (Per Quart).....XT-12 QULV

FORD 6F35

NO OR INTERMITTENT LOSS OF REVERSE



Figure 1




Figure 2