


2015 HONDA FIT CVT GTAA**DTC U0401**

COMPLAINT: After transmission repairs are made which required transmission removal you may encounter a DTC U0401-68. This code will set after reaching 30 MPH. All OEM diagnostic procedures indicate a faulty ECM module or updated programming is required. Note: The vehicle did not have this problem prior to removal of the transmission.

CAUSE: It was discovered that there was no drive pulley signal while road testing the vehicle. The drive pulley sensor had a poor connection at the connector pins. See figure 1.

CORRECTION: Resize the pin connectors and apply Stabilant 22 contact enhancer.

**Figure 1**