



THM 4T65-E

RATTLING NOISE WITH ENGINE RUNNING


COMPLAINT: Some vehicles equipped with the THM 4T65-E transaxle may exhibit a rattling noise coming from the area of the side cover, and may occur in any gear.

CAUSE: The cause may be, the locating dowels (rivets) being loose in the input speed sensor reluctor wheel. Refer to Figure 1.

CORRECTION: Replace the input speed sensor reluctor wheel with updated OEM part number 24212217.

SERVICE INFORMATION:

Input Speed Sensor Reluctor Wheel 24212217



Copyright © 2002 ATSG