



# Technical Service Information

---

## 4F27E/FNR5

### SLIPPING OR NO REVERSE

**COMPLAINT:** A vehicle equipped with a 4F27E or FNR5 may have a complaint of a badly slipping or no reverse condition. The vehicle may have come in with this complaint and can still have it after overhaul.

**CAUSE:** The reverse air bleed capsule in the rear cover is leaking due to a deformed check-ball (figure 1).

**CORRECTION:** Check the replacement rear cover by blocking the reverse clutch feed hole in the sealing ring area. Then, wet air check the “To Reverse Clutch From Main Valve Body” circuit shown in figure 2 to ensure the check-ball does not leak. Once verified, install the replacement cover.

## 4F27E/FNR5 SLIPPING OR NO REVERSE




Figure 1




Figure 2