



Technical Service Information

HONDA CIVIC B4RA-M4RA-BMXA FAMILY WRONG GEAR STARTS-MULTIPLE SHIFT COMPLAINTS

COMPLAINT: After overhaul, Honda Civics equipped with the B4RA, M4RA and or BMXA transaxle may exhibit wrong gear starts or multiple shift complaints.

CAUSE: The cause may be, that during overhaul of the valve body and re-assembly one or more of the feed tubes were placed into the wrong hole on the accumulator body or valve body, causing low modulating pressure , which is solenoid feed and or low clutch apply pressure to one or more of the clutch packs.

CORRECTION: To correct this condition, refer to Figure 1 and measure the feed tube lengths to ensure that they are going into the correct locations on the accumulator body and valve body.

HONDA CIVIC

FEED TUBE LOCATIONS B4RA-M4RA-BMXA FAMILY




Figure 1