



# Technical Service Information

---

## **FORD 6R80**

### **P0741 SET AFTER OVERHAUL**

**COMPLAINT:** A 2015 Ford Transit 150 equipped with the 6R80 transmission sets trouble code P0741 for TCC Stuck Off and P1744 for Torque Converter Clutch System Performance.

**CAUSE:** The forward most sealing ring on the 4-5-6 Clutch Housing/Input shaft was accidentally not installed by the builder, refer to figure 1.

**CORRECTION:** The 4-5-6 Clutch Housing/Input Shaft requires three sealing rings as seen in figure 2.

## 6R80 P0741 SET AFTER OVERHAUL

### 4-5-6 CLUTCH HOUSING/INPUT SHAFT




Figure 1




Figure 2

Copyright © 2020 ATSG