


SUBARU CVT LINEARTRONIC TR580 SPEED SENSOR CODES

COMPLAINT: A Subaru Legacy with a 2.5L engine and TR580 Lineartronic CVT transmission comes into your shop setting random speed sensor codes P2747 and P2751.

CAUSE: Both speed sensors share a common ground that is often compromised from windshield water run off. See figures 1 and 2.

CORRECTION: Clean the ground wire connection on the top of the transmission.



Copyright © ATSG 2021

Figure 1




Figure 2