

NISSAN VERSA

TRS CODE P0705 SET

COMPLAINT: A 2012 to 2014 Nissan Versa Sedan may have complaints of a hesitation on acceleration, the cvt transmission is not shifting properly and a trouble code P0705 for "Transmission Range Sensor A Circuit" is set.

CAUSE: These complaints can be caused by corrosion in the reverse/tail lamp sockets due to water intrusion, refer to figure 1 and 2 or corrosion on the lamp assembly circuit board, see figure 3. It can also be caused by the use of an incorrect bulb.

CORRECTION: If the bulb sockets show signs of corrosion, they must be thoroughly cleaned or replaced. If the circuit board show signs of corrosion, the lamp assembly will require replacement. Ensure that the correct bulb is used for each location needing replacement.
Make certain the tail lamp grounds located behind the rear seat side panels are not compromised.




Figure 1

NISSAN VERSA
TRS CODE P0705 SET




Figure 2




Figure 3