SUBARU TR580 CVT

FLUID SERVICE PLUG CHANGE

CHANGE: The fluid service plug for the CVT check plug, the front differential fill plug and the front differential drain plug locations has gone from 10mm in length to 14.7mm in length, refer to figure 1, on TR580 CVT transmissions built before March 1, 2015. Any TR580 built after this date will have the 14.7mm installed.

REASON: The 14.7mm plug further distributes the forces applied to the threads and decreases the possibility of damage to the transmission case and converter housing (stripped threads).

PARTS AFFECTED:

The fluid service plug. The service plugs affected are shown in figure 2.

NOTE: New and remanufactured transmissions are shipped dry. The service plugs are installed partially tightened.

INTERCHANGEABILITY:

The 14.7mm fluid service plug will back service all TR580 transmissions.

SERVICE INFORMATION:

14.7mm Fluid Service Plug.....807018070

SUBARU TR580 CVT

FLUID SERVICE PLUG CHANGE



Figure 1



Figure 2