



Technical Service Information

2009 ATSG BULLETIN INDEX

09-01	GM 6T70/75E	I PRELIMINARY INFORMATION
09-02	GM 4L80-E	NEUTRAL DURING OR AFTER SHIFT TO 4TH
09-03	CHRYSLER 48RE	48RE VALVE BODY HYDRAULIC DIFFERENCES
09-04	CHRYSLER NAG1, 42RLE, CVT MODELS	DIPSTICK USE
09-05	FORD 5R110W	P0657 LOSS OF ACTUATOR SUPPLY VOLTAGE
09-06	FORD 4R70W-4R70/75E	NO SPEED OR SLOW SPEED O-READING
09-07	NISSAN RE5R05A	VALVE BODY IDENTIFICATION
09-08	BMW/ISUZU 4L30E	INADEQUATE LINE RISE
09-09	VW-AUDI 01M/01N/01P	3-4 UP-SHIFT FLAIR
09-10	BMW ZF6HP26	STUCK IN PARK
09-11	HONDA BAXA/B7XA FAMILY	FLARES OR SLIPS ON UPSHIFTS (COMMONLY COLD)
09-12	SUBARU 4-AT 98 & UP	DELAYED OR NO FORWARD ENGAGEMENT
09-13	FORD AX4S	1-2 NEUTRAL (1999 & UP)
09-14	FORD 4F50N	1-2 SLIDE BANG UPSHIFT
09-15	FORD 5R110W	ERRATIC SHIFTS AND TFT GAGE OPERATION
09-16	DODGE CHRYSLER JEEP 45RFE	NO MOVE AFTER OVERHAUL
09-17	TOYOTA U240E	VALVE BODY REPAIR INFORMATION
09-18	HYUNDAI A4AF3/A4BF2	PRELIMINARY INFORMATION
09-19	HONDA/ACURA MGHA FAMILY	WRONG GEAR STARTS/VARIOUS SOLENOID CODES
09-20	HONDA BAXA/B7XA	P1705 DIAGNOSIS
09-21	GM-ALLISON 1000/2000 (2006 UP MODELS)	P0708 INTERNAL MODE SWITCH DIAGNOSIS
09-22	GM/BMW 5L40	1-2 BIND UP (SAFETY MODE VALVE STRATEGY)
09-23	ALLISON 1000/2000	UPDATED DIAGNOSTIC TROUBLE CODE DESCRIPTIONS
09-24	ALLISON 1000/2000	TORQUE CONVERTER CLUTCH CYCLING
09-25	ALLISON MT545	ELECTRIC MODULATOR OPERATION
09-26	GM TOW/HAUL MODE	TOW/HAUL SWITCH DIAGNOSIS
09-27	DODGE/CHRYSLER 41TE/42LE	PRNDL MALFUNCTION
09-28	DODGE/CHRYSLER (Various trans types)	ELECTRONIC TESTING CONSISTENCY

AUTOMATIC TRANSMISSION SERVICE GROUP



Technical Service Information

2009 ATSG BULLETIN INDEX

09-29	FORD AX4S (99&UP)	N-D DELAY/BANG ENGAGEMENT
09-30	DODGE/CHRYSLER/JEEP 45RF3	TORQUE CONVERTER CLUTCH ENGAGEMENT ISSUES
09-31	FORD TARUS/SABLE AX4S/AX4N	MLP/DTR DIAGNOSIS
09-32	DODGE RWD 46-47-48RE	PUSH-IN TRS DIAGNOSIS AND SERVICE
09-33	FORD AX4N/4F50N	N-D DELAY/BANG ENGAGEMENT
09-34	FORD AX4S/AX4N/4F50N	NO THIRD GEAR
09-35	SUBARU 4-AT PHASE II	NO REVERSE
09-36	BMW/ISUZU 4L30-E	NO REVERSE BINDS IN 2ND
09-37	ISUZU 4L30-E	VARIOUS ELECTRICAL COMPONENT CODES STORED (Case Connector I.D. for 2000 up)
09-38	NISSAN RE4R01A/RE4F04A	DELAY 1-2 AND OVER-SPEED ON 2-3 UPSHIFT
09-39	BMW ZF6HP26	FLUID LEAK FROM CASE CONNECTOR
09-40	MERCEDES 722.6	TCM FLUID CONTAMINATION
09-41	ALLISON 1000/2000	DTC P0735 ON HIGHWAY
09-42	GM 6T70/75	INPUT/OUTPUT SENSOR ISSUES
09-43	SATURN VUE/ION AF33-5	2-3 FLARED UPSHIFT
09-44	SATURN VUE AF33-5	P0717 DIAGNOSIS

AUTOMATIC TRANSMISSION SERVICE GROUP