



# Technical Service Information

## 2010 ATSG BULLETIN INDEX

10-01	NISSAN RE4R01A	LOW/REVERSE ANTI RATTLE CLIP LOCATION
10-02	ISUZU/HONDA 4L30-E	4TH GEAR STARTS, HARSH 2-3/HARSH DOWNSHIFTS
10-03	FORD 500/FREESTYLE/MONTEGO "CVT"	VARIOUS NOISES FROM TRANSAXLE
10-04	FORD/MAZDA FNR5/5NR5	PRELIMINARY INFORMATION
10-05	CHRYSLER/DODGE 41TES/42RLE VLP	VARIABLE LINE PRESSURE SOLENOID AND SENSOR
10-06	GM CHEVY AVEO AW 81-40 LE	PRELIMINARY INFORMATION
10-07	FORD 4R100	DIAGNOSTIC TROUBLE CODES P0715-P0717 DIAGNOSIS
10-08	FORD AX4N/4F50N (99&UP)	DELAY OR SLIPS IN REVERSE
10-09	FORD 5R110W	DELAYED ENGAGEMENTS / LOW PRESSURE
10-10	FORD 4R70W/4R75E	3-4 NEUTRAL OR SLIPS IN 4TH
10-11	TOYOTA/LEXUS U140/U240	ENGAGEMENT ISSUES IN REVERSE AND OR 4TH
10-12	NISSAN RE5R05A	TCM FUSE BLOWS (LATE 04 AND UP MODELS)
10-13	GM/VOLVO/NISSAN AW55-50	VALVE BODY I.D. FOR SERVICE
10-14	NISSAN RE5R05A	HIGH AND LOW REVERSE CLUTCH SCALLOPED SEALING RING LOCATION
10-15	MERCEDES BENZ 722.9	PRELIMINARY INFORMATION
10-16	CHRYSLER 62TE	PRELIMINARY INFORMATION
10-17	GM 4L60/70E	2009 MODEL YEAR CHANGES
10-18	TOYOTA/LEXUS U140/240E	NO 4TH AND ENGINE RELATED TROUBLE CODES
10-19	GM 6L80	SLIPS FORWARD P2728
10-20	GM/BMW 5L40E	ACCUMULATOR SPRING SPECS AND I.D.
10-21	HONDA/ACURA MGHA 5 SPEED	NEUTRAL ON DOWNSHIFT TO 1ST
10-22	FORD 5R55W/S	WATER IN TRANSMISSION FLUID
10-23	HONDA/ACURA BAXA/B7XA	TIE UP IN REVERSE HOT
10-24	GM 4T60/65E	TCC STUCK OFF P0741
10-25	VW 09A(JF506E) 09G(TF60-SN)	2-3 FLARE 3-4 HARSH SHIFT OR HARSH DOWNSHIFTS
10-26	GM 4L60/65/70E	PUMP AND INPUT SHAFT USAGE

## AUTOMATIC TRANSMISSION SERVICE GROUP