



Technical Service Information

2012 ATSG BULLETIN INDEX

12-01	HONDA/ACURA(5 SPD)	AT CONTROL LEVER CHANGES FOR “05’ MDX
12-02	HONDA/ACURA MGHA FAMILY(5 SPD)	COUNTER SHAFT SPEED SENSOR BREAKAGE
12-03	HONDA/ACURA MGHA FAMILY(5 SPD)	AT SHOCK OR NOISE DURING ENGAGEMENTS
12-04	DODGE 46RE	INTERMITTENT NO UP-SHIFT/SPEEDO PROBLEMS
12-05	HYUNDAI F4A40 (05 ELANTRA)	2-3 BIND OR DOUBLE BUMP COLD ONLY
12-06	DODGE 45/545/68RFE	DELAYED ENGAGEMENTS AFTER <i>COOLER</i> FILTER REPLACEMENT
12-07	DODGE 45/545/68RFE	DELAYED ENGAGEMENTS AFTER <i>SUMP</i> FILTER REPLACEMENT
12-08	DODGE/CHRYSLER 31TH/41TE/41TES 42RLE/62TE	FINAL DRIVE RATIO I.D. AND MODEL I.D. FOR 1998-2012
12-09	FORD CFT30/CVT TRANSMISSION	TURBINE SHAFT SEALING RING CHANGE
12-10	4AT PHASE II VERSION II (04&UP)	CONTROL AND VALVE BODY CHANGES (PRELIMINARY INFORMATION)
12-11	GM 6L80	SLIPS IN REVERSE/SLIPS ON THE 2-3 UP-SHIFT

AUTOMATIC TRANSMISSION SERVICE GROUP