



Technical Service Information

2012 ATSG BULLETIN INDEX

12-01	HONDA/ACURA(5 SPD)	AT CONTROL LEVER CHANGES FOR “05’ MDX
12-02	HONDA/ACURA MGHA FAMILY(5 SPD)	COUNTER SHAFT SPEED SENSOR BREAKAGE
12-03	HONDA/ACURA MGHA FAMILY(5 SPD)	AT SHOCK OR NOISE DURING ENGAGEMENTS
12-04	DODGE 46RE	INTERMITTENT NO UP-SHIFT/SPEEDO PROBLEMS
12-05	HYUNDAI F4A40 (05 ELANTRA)	2-3 BIND OR DOUBLE BUMP COLD ONLY
12-06	DODGE 45/545/68RFE	DELAYED ENGAGEMENTS AFTER <i>COOLER</i> FILTER REPLACEMENT
12-07	DODGE 45/545/68RFE	DELAYED ENGAGEMENTS AFTER <i>SUMP</i> FILTER REPLACEMENT
12-08	DODGE/CHRYSLER 31TH/41TE/41TES 42RLE/62TE	FINAL DRIVE RATIO I.D. AND MODEL I.D. FOR 1998-2012
12-09	FORD CFT30/CVT TRANSMISSION	TURBINE SHAFT SEALING RING CHANGE
12-10	4AT PHASE II VERSION II (04&UP)	CONTROL AND VALVE BODY CHANGES (PRELIMINARY INFORMATION)
12-11	GM 6L80	SLIPS IN REVERSE/SLIPS ON THE 2-3 UP-SHIFT
12-12	AUDI, PORSCHE, SAAB, VOLVO 09G, 09D, TF80, AW55-50SN	VARIOUS SHIFT COMPLAINTS
12-13	DODGE/JEEP 45/545RFE	DRIVELINE “PING” ON ENGAGEMENT IN OR OUT OF THE PARK POSITION
12-14	MERCEDES BENZ 722.9	DELAYED REVERSE APPLICATION (RE-LEARN)
12-15	DODGE/CHRYSLER 62TE	GEAR RATIO ERRORS
12-16	TOYOTA RAV-4 U140-240	PCM WARRANTY ENHANCEMENT
12-17	GM 4479 TRANSFER CASE	TIMED PLANETARY ALIGNMENT FOR INSTALLATION
12-18	GM 4L60/65/70E	P0894 TCC SLIP
12-19	DODGE/CHRYSLER 62TE	NO REVERSE, NO 3RD
12-20	DODGE/CHRYSLER 62TE	1-2 OR 2-3 NEUTRAL
12-21	FORD 5R55W/S	2-3 FLARE AND OR NO 3RD
12-22	VW/AUDI 01M/01N/01P	LATE UPSHIFTS WHEN HOT
12-23	NISSAN RE4F04B, RE4F03B	HARSH 1-2 UPSHIFT AND OR P0745
12-24	VW 09A JF506E	NO UPSHIFT COLD
12-25	VW/AUDI/PORSCHE 09D	TORQUE CONVERTER AND VALVE BODY DIFFERENCES

AUTOMATIC TRANSMISSION SERVICE GROUP



Technical Service Information

2012 ATSG BULLETIN INDEX

12-26	HONDA ODYSSEY 07-2010 (5 SPD)	TCC VIBRATION BETWEEN 30 TO 40MPH PGRA-P36A TRANSTYPE
12-27	AUDI 01J (CVT)	SHUDDER ON TAKEOFF
12-28	AUDI 01J (CVT)	ENGAGEMENT ISSUES
12-29	AUDI 01J (CVT)	ADAPTATION- ENGAGEMENT RELEARN
12-30	AUDI 01J (CVT)	FORWARD DRUM AND PULLEY SERVICE
12-31	TOYOTA 540/541E	ENGINE CHUG COMING TO A STOP
12-32	BMW/FORD 6HP26/6R60	3-4 OR 4-5 FLARE
12-33	NISSAN/INFINITI RE5R05A	GEAR RATIO ERRORS AND/OR TCM COMPATIBILITY
12-34	NISSAN/INFINITI RE5F22A	FAILSAFE DIAGNOSTIC TROUBLE CODE P0726
12-35	NISSAN/INFINITI RE4F04B	NO TURBINE SHAFT READING

AUTOMATIC TRANSMISSION SERVICE GROUP