

2026 ATSG BULLETIN INDEX

26-01	DODGE	68RFE	2019 Valve Body & Pump Changes
26-02	FORD	10R60	Harsh 7-6 Downshift
26-03	JEEP CHEROKEE	948TE	Delayed Reverse-Limp Mode
26-04	DODGE	62TE	Aerated Fluid, Inconsistent Fluid Level
26-05	GM	8L90	Reverse In All Gear Shift Positions
26-06	GM	6T70	No Communication With TCM
26-07	SUBARU	TR690 & TR580	CVT Solenoid Id
26-08	FORD	10R80	High Pitched Whine
26-09	HYUNDAI-KIA	A6 Series	No Movement After VB Replacement
26-10	GM	10L1000	Binding Up On Shifts
26-11	GM/FORD	6T40/6F35	Turbine Shaft Interchange
26-12	Hyundai	A6GF1	DTC P0732 Before and After Rebuild
26-13	FORD	8F35/40	Preliminary Information
26-14	FORD	6F35	Transmission Over Temp Condition
26-15	GM CHEVY SPARK	CVT7(JF015E)	No Converter Clutch Application
26-16	GM	9T60/9T65	Momentary Neutral
26-17	FORD	4R75	Brutal 1-2 After Rebuild
26-18	DODGE	RFE Series	Drain Back Issues
26-19	FORD	8F35	IN & Out of L/U Before/After Rebuild
26-20	HYUNDAI/VELOSTER	D6GF1	No Engagements
26-21			
26-22			
26-23			
26-24			
26-25			
26-26			

2026 ATSG BULLETIN INDEX

26-27

26-28

26-29

26-30

26-31

26-32

26-33

26-34

26-35

26-36

26-37

26-38

26-39

26-40