




SUSI Adapters, Inc.

Wiring Diagram for Schneider 7400 Series meter in a GE DS-67 case
(Two 2 Element meters) SUSI # SWDG675-7400
with Power Connected to Phase A



Notes:

1. The jumpers from I_A^- to I_C^- may not be needed if there is already an external jumper on the back of the case.
2. Fuses are recommended

610-1519-00-A

Back View