



Technical Service Information

2010 ATSG BULLETIN INDEX

10-01	NISSAN RE4R01A	LOW/REVERSE ANTI RATTLE CLIP LOCATION
10-02	ISUZU/HONDA 4L30-E	4TH GEAR STARTS, HARSH 2-3/HARSH DOWNSHIFTS
10-03	FORD 500/FREESTYLE/MONTEGO "CVT"	VARIOUS NOISES FROM TRANSAXLE
10-04	FORD/MAZDA FNR5/5NR5	PRELIMINARY INFORMATION
10-05	CHRYSLER/DODGE 41TES/42RLE VLP	VARIABLE LINE PRESSURE SOLENOID AND SENSOR
10-06	GM CHEVY AVEO AW 81-40 LE	PRELIMINARY INFORMATION
10-07	FORD 4R100	DIAGNOSTIC TROUBLE CODES P0715-P0717 DIAGNOSIS
10-08	FORD AX4N/4F50N (99&UP)	DELAY OR SLIPS IN REVERSE
10-09	FORD 5R110W	DELAYED ENGAGEMENTS / LOW PRESSURE
10-10	FORD 4R70W/4R75E	3-4 NEUTRAL OR SLIPS IN 4TH
10-11	TOYOTA/LEXUS U140/U240	ENGAGEMENT ISSUES IN REVERSE AND OR 4TH
10-12	NISSAN RE5R05A	TCM FUSE BLOWS (LATE 04 AND UP MODELS)
10-13	GM/VOLVO/NISSAN AW55-50	VALVE BODY I.D. FOR SERVICE
10-14	NISSAN RE5R05A	HIGH AND LOW REVERSE CLUTCH SCALLOPED SEALING RING LOCATION

AUTOMATIC TRANSMISSION SERVICE GROUP