



Technical Service Information

2013 ATSG BULLETIN INDEX

13-01	BMW	4L30,5HP19,24,6HP26	NO 4TH, 5TH AND OR WRONG GEAR STARTS NO TRANSMISSION DTC'S
13-02	BMW	5HP24	NEUTRAL OR SLIPS ON TAKE-OFF IN DRIVE
13-03	FORD	LINCOLN LS 5R55S	HARSH ENGAGEMENTS OF HARSH SHIFTS
13-04	DODGE	518,46-47 RE- UNITS	TCC CYCLING (COMPLETE LIST)
13-05	FORD	6R140	PRELIMINARY INFORMATION
13-06	DODGE	45/545RFE	REPEAT TRANS FAILURE/FLARED SHIFTS
13-07	DODGE	NAG-1	TRANSMISSION OVERHEAT
13-08	DODGE	45/545/68RFE	LUBE CIRCUIT AND PUMP CHANGES
13-09	DODGE	545RFE	06-UP TRUCK PARTIAL TCC SHUDDER
13-10	TOYOTA	U660	PRELIMINARY INFORMATION
13-11	DODGE/ISUZU MITSU FUSO	AS68RC	TORQUE CONVERTER OVERHEAT K2 FAILURE
13-12	DODGE/ISUZU MITSU FUSO	AS68RC	NO FORWARD IN "D" MOVES IN MANUAL "1"
13-13	AUDI/VW/MINI 09G/09M TF60-SN		PRELIMINARY INFORMATION
13-14	AUDI/VW/MINI 09G/09M TF60-SN		VAG (VCDS) TRANS DATA PARAMETERS AND COMMON DTC DESCRIPTIONS
13-15	FORD 6R80		CONTROL MODULE CHANGES
13-16	DODGE 48RE		PARTIAL ENGINE STALL IN DRIVE
13-17	GM 6L80/90		FLARE 2-3 ENGAGEMENT CONCERNS (NEW PUMP COVER RINGS)
13-18	HONDA/ACURA V6 5SPEED		OVERHEATED TORQUE CONVERTER

AUTOMATIC TRANSMISSION SERVICE GROUP