



Technical Service Information

2016 ATSG BULLETIN INDEX

16-01	TOYOTA	A245E/246E	VALVE BODY IDENTIFICATION
16-02	HYUNDAI / KIA.	A6MF1	6 SPEED TRANSMISSION
16-03	G.M	6T40	BUMPY OR SLIPPING REVERSE, THIRD AND FIFTH
16-04	G.M	6L50/80/90	INTERMITTENT FAILSAFE AFTER PULLING LOAD OR KICK-DOWN
16-05	SUBARU LINEARTRONIC CVT		PRELIMINARY INFORMATION
16-06	TOYOTA	A750/A761/AB60	DIAGNOSING PERFORMANCE DTC'S
16-07	DODGE	45/545/68RFE	DELAY/SHUDDER DURING DRIVE ENGAGEMENT
16-08	DODGE	AS68RC	VARIOUS SHIFT TRANSITION COMPLAINTS
16-09	FORD	6R140	VALVE BODY VARIATIONS
16-10	GM	6T30/40/45/50	GENERATION I & II INFORMATION
16-11	GM eASSIST BAS	HYBRID SYS	PRELIMINARY INFORMATION
16-12	ALLISON	1000/2000 6 SPD	2010 UPDATES
16-13	DODGE	AS68RC	VALVE BODY DIFFERENCES
16-14	LEXUS	A960E	PRELIMINARY INFORMATION
16-15	VW/AUDI	09G/M T F60-SN	DRAG OR PARTIAL BIND ON TAKEOFF
16-16	KIA	5HF1_F5A51	NO FORWARD OR UNDERDRIVE CLUTCH DRUM FAILURE
16-17	TOYOTA	U660E	TCM ELIMINATED
16-18	G.M.	4T40/65/80-4L80E	P0730 GEAR RATIO ERROR
16-19	FORD	5R110W	INTERMITTENT SOLENOID CODES
16-20	DODGE CHARGER	NAG 1	DRIVELINE VIBRATION-SHUDDER STOPPING
16-21	DODGE	AS68RC	COOLER LINE RETAINING CLIPS
16-22	FORD	6R60-75-80	DELAY REVERSE AND OR 2-3 FLARE
16-23	FORD	6R60-75-80	FLARED SHIFT INTO 4TH-5TH-6TH HOT
16-24	FORD	6F35	HARSH SHIFTS OR ENGAGEMENTS
16-25	FORD	6F35	HARSH REVERSE-HARSH 2-3 SHIFT
16-26	FORD	4R75E	PLANETARY FAILURE
16-27	FORD MAZDA	4R44-5R55	ENGINE DAMAGE DURING R&R
16-28	CHRYSLER	62TE	SEVERE 2-3 BIND

AUTOMATIC TRANSMISSION SERVICE GROUP



Technical Service Information

16-29	FORD-MAZDA	4F27E-FNR5-5NR5	1-2 FLARE OR SLIDE BUMP
16-30	FORD	5R55S	VALVE BODY CHANGES FOR 2009 AND UP MODELS
16-31	FORD	5R55S	P0713- VARIOUS SOLENOID FAULTS-TCC CYCLING
16-32	BMW	ZF6HP FAMILY	PLANETARY NOISE ALSO WHEN STOPPED IN DRIVE
16-33	MITSUBISHI	F4A50 SERIES	HARSH OR FLARED 2-3/3-2 AND OR GEAR RATIO ERRORS
16-34	TOYOTA	U150-250	DOWNSHIFT CLUNK FROM 5TH OR 4TH GEAR
16-35	DODGE	AS68RC	PRESSURE SWITCH FAULT AFTER REPLACEMENT
16-36	GM	AF23-33	VALVE BODY ASSEMBLY INFORMATION ONLY
16-37	CHRYSLER	62TE	MANUAL SELECTOR SHAFT SEAL LEAKAGE
16-38	BMW	ZF5HP24	DELAY/SLIPS IN REVERSE
16-39	BMW	ZF6HP19/26	REVERSE AND/OR DRIVE ENGAGEMENT COMPLAINTS
16-40	ACURA		DTC P0740 AND TCS 31-2