



Technical Service Information

2020 ATSG BULLETIN INDEX

20-01	FORD	6F35	AXLE SEAL USAGE
20-02C	GM	8L,10L SERIES	SHUDDER DURING ACCELERATION
20-03	GM	6T & 6L SERIES	SOLENOID & TCC PERFORMANCE CODES
20-04	GM	6T40 GEN III	OFF AXIS PUMP ASSEMBLY
20-05	GM	9T50	DTC P0747 SET AT ENGINE STARTUP
20-06	GM	10L90	VALVE BODY PART UNIQUE NUMBER
20-07	DODGE/JEEP	42RE/46RE	NO MOVEMENT
20-08	DODGE	66RFE	CLUTCH NOISE
20-09	TOYOTA	A750E	HARSH 2-3 SHIFT
20-10	MITSUBISHI FUSO	DUONIC DSG	CODE RETRIEVAL PROCEDURE
20-11	GM	6T70-75	NO REVERSE, 3RD OR 5TH GEARS
20-12	HONDA	BMXA	FEED TUBE LOCATIONS
20-13	HONDA/ACURA	ALL 5 SPEEDS	SPRAG ROTATION
20-14	GM	6T70-75	DTC P0741 SET
20-15	HONDA	6 SPEED	PRESSURE PORT LOCATION & SPECIFICATIONS
20-16	GM	6T, 6L, 8L SERIES	MISSING GEARS
20-17	GM	6T40 SERIES	GENERATION 3 CHANGES
20-18	GM	6T40 SERIES	LOSS OF OSS SIGNAL
20-19	GM	6T40 SERIES	BUMP, SURGE
20-20	GM	6T40 SERIES	NEUTRAL IDLE CONTROL
20-21	GM	6T40 SERIES	NO FORWARD MOVEMENT OR SLIPPING
20-22	FORD	DPS6 DCT	HILL START ASSIST
20-23	FCA	41TE	DELAYED ENGAGEMENT
20-24	FORD	6R80	P0741 SET AFTER OVERHAUL
20-25	FORD	6R140W - 6R80	CENTER GEAR CASE ASSEMBLY
20-26	GM	6L80/90	HARSH/ABRUPT UP & DOWN SHIFTS
20-27	FORD	AWD	PTU INTERMEDIATE SHAFT SEAL LEAK
20-28	GM	6T40 HYBRID	LOSS OF LINE PRESSURE

AUTOMATIC TRANSMISSION SERVICE GROUP



Technical Service Information

2020 ATSG BULLETIN INDEX

20-29	HONDA ODYSSEY	B36A	MISSING 2ND GEAR
20-30	HONDA PILOT	5 SPEED	“D” & VTM-4 LAMPS ILLUMINATED
20-31	HYUNDAI/KIA	A6MF1	P0753 SET-SHIFT SOLENOID ‘A’
20-32	NISSAN VERSA	CVT	LOSS OF ENGINE POWER ON INITIAL TAKE-OFF
20-33	PORSCHE CAYENNE	09D	4 WHEEL DRIVE WARNING LAMP ILLUMINATED
20-34	TOYOTA	AB60E	DTC 2714 SET
20-35	SUBARU	LINEARTRONIC	TORQUE CONVERTER CHANGE
20-36	NISSAN/INFINITI	RE5R05A	STUCK IN FIRST GEAR

AUTOMATIC TRANSMISSION SERVICE GROUP