Technical Service Information

2021 ATSG BULLETIN INDEX

21-01	TOYOTA	A340 SERIES	CHECKBALL & SMALL PARTS LOCATIONS
21-02	LAND ROVER	ZF8HP70	TRANSMISSION CASE OIL LEAK
21-03	GM	8L90	SHIFTS 3-NEUTRAL
21-04	GM	8L90	INCREASED THROTTLE PEDAL EFFORT
21-05	MERCEDES BENZ	722.6	BUZZING NOISE
21-06	SUBARU	TR580 CVT	FLUID SERVICE PLUG CHANGE
21-07	GM	6T70	SECOND GENERATION CHANGES
21-08	GM	6L80	DELAYED REVERSE ENGAGEMENT WHEN HOT
21-09	FORD	5R110W	FRONT PUMP DAMAGE
21-10	FORD	6R140W	TRANSMISSION COOLING UPGRADE

Technical Service Information

2021 ATSG BULLETIN INDEX

AUTOMATIC TRANSMISSION SERVICE GROUP