



Technical Service Information

2007 ATSG BULLETIN INDEX

07-01	GM 4T65E	FORWARD AND REVERSE SERVO BOOST VALVE
07-02	GM 4T40E	SLIPS FORWARD AND/OR REVERSE
07-03	GM 4T40/45E	DTC P1810
07-04	GM SATURN TAAT	HARSH SHIFTS P0746/ P0789
07-05	FORD 4R70E/4R75E	CHANGES FOR 2004
07-06	BMW-AUDI-VW ZF5HP19 FL/FLA	PARTS MIS-MATCH
07-07	LEXUS A761E	PRELIMINARY INFORMATION
07-08	FORD 4R70E/4R75E	P0715/P0717 OR ERRATIC SHIFTS
07-09	MERCEDES 722.6	PRINCIPLES OF OPERATION
07-10	FORD 4R70W (96 AND UP)	NEUTRAL ON TAKE-OFF
07-11	FORD AX4S	NEW INTERNAL COOLER BYPASS CIRCUIT
07-12	GM 4T65E	P0742 TCC STUCK ON (IN DEPTH DIAGNOSIS)
07-13	GM 4T65E	P1887 TCC RELEASE SWITCH DIAGNOSIS
07-14	BMW ZF5HP24	E CLUTCH FEED PIPE DAMAGE
07-15	VW/AUDI ZF5HP19 FL/FLA	NO REVERSE
07-16	VW/AUDI 01M-95-97	NEUTRAL INTO 4TH
07-17	MERCEDES 722.6	K3 HUB AND REAR SUN GEAR ASSEMBLY DIFFICULTIES
07-18	MERCEDES 722.6	SHIFT AND TCC COMPLAINTS
07-19	CHRYSLER	PCI DIAGNOSIS
07-20	DODGE 42LE	DTC P1695 - P1698
07-21	SATURN	NEW ACTUATORS 2000-UP
07-22	DODGE RWD	TRANSMISSION RANGE SENSOR

AUTOMATIC TRANSMISSION SERVICE GROUP