




Wiring Diagram for Siemens PAC3100/3200/4200 Panel Adapter in a GE Large case with Control Power Connected SUSI Adapters #SWDGL9-PAC



Back View

Notes:

1. Factory connected A phase voltage to Control Power to power the meter electronics.
2. Connect "GND" as needed
3. Fuses are recommended.