




Wiring Diagram for PM5500 Series meter in a GE small case (2 1/2 Elements) with Power Supply Connected, SUSI Adapters # SWDGS6-PM55



Notes:

1. Connect "GND" as needed during Installations.
2. Fuses are recommended
3. Optional Pulse Outputs (KYZ)-
D1+ to Z or Y ; D1- to K