




Wiring Diagram for Electro Industries Shark 100S/200S in a GE small case with Power Supply Connected SUSI Adapters # SWDWGS5



Front View

Notes:

1. Factory connected A phase voltage to L1 and L2 for powering the meter electronics.
2. Connect "GND" as desired.
3. Current wire 16 AWG
4. Voltage wire 18 AWG

610-1502-50-A