




Wiring Diagram for Siemens PAC 3100/3200/4200 Panel Adapter for GE medium case SUSI # SWDG436-PAC with control power connected to A phase



Connection type 3P3W, with two voltage transformers, with three current transformers