




Wiring Diagram for PM 5000 & 8000 Series meter in a GE small case with Power Supply Connected, 3-element SUSI Adapters # SWDGS9-5000, & # SWDGS9-8000



Notes:

1. Connect GND to the meter as needed during installation.
2. Fuses are recommended.

Back View