




Wiring Diagram for Schneider Electric ION 7400, PM 5000 & PM 8000 Series meter in a GE small case with Power Supply Connected, 3-element, ESK & KYZ Optional SUSI Adapters # SWDGS9-74, SWDGS9-5000, & SWDGS9-8000



Notes:

1. Factory connected A phase voltage to the control power of meter
2. Connect GND to the meter as needed during installation.
3. Fuses are recommended.

Back View