




Wiring Diagram for Schneider PM 5500 series meter in a SUSI Adapters # SWF3710-5000



Back View

610-3710-55-B