



# Technical Service Information

## 2005 ATSG BULLETIN INDEX

05-01	CHRYSLER 45RFE	NO 3RD OR 4TH GEAR
05-02	FORD 5R110W Torqshift	LOW DIODE FAILURE
05-03	FORD 5R110W Torqshift	INTERNAL HARNESS OR SOLENOID BODY CHANGE
05-04	FORD 5R110W Torqshift	NEW REAR PLANETARY (PLANETARY FAILURE)
05-05	SATURN AF23/33-5	PRELIMINARY INFORMATION
05-06	HONDA CVT	PRELIMINARY INFORMATION
05-07	FORD, JAGUAR, MAZDA JF506-E ROVER, VW	2-3 FLARE OR SLIPS 3RD, 4TH, 5TH
05-08	ISUZU, BMW 4L30-E	DTC P01870 OR TCC SHUDDER
05-09	MITSUBISHI F4A41, F4A51	VALVE BODY EXPLODED VIEWS
05-10	FORD 5R55N, 5R55W/S	FALSE PRESSURE CONTROL SOLENOID CODES
05-11	FORD 5R110W	FORWARD CLUTCH CHANGES FOR 2005
05-12	FORD 5R110W	NEW INTERMEDIATE CLUTCH PLATES AND DIRECT CLUTCH HOUSING FOR 2005
05-13	FORD E4OD	CONCERNS ON NEW CASE FROM FORD
05-14	FORD AX4N	HARSH UP-SHIFTS AND DOWNSHIFTS
05-15	NISSAN RE4F04A	P0745 HARSH UP-SHIFTS
05-16	VW 01M	VALVE BODY CHANGES FOR LATE 98 AND UP
05-17	FORD 4F27E	NEUTRAL IN 4TH GEAR
05-18	FORD 4R70W	EPC PRESSURE LOSS, SOFT OR SLIPPING UP-SHIFTS
05-19	FORD AX4N	1999 AND UP, NEUTRAL ON TAKE-OFF FOR FLAIED 1-2
05-20	FORD 5R55N	REVISED CHECK BALL LOCATIONS
05-21	FORD 5R55N	SLIPS ON THE 2-3 UP-SHIFT
05-22	JF506E	NO REVERSE, SLIPS FORWARD
05-23	4T65-E	NO 1ST OR 4TH, 2ND AND 3RD GEAR ONLY
05-24	4T65-E	ERRATIC OR NO INPUT SPEED SIGNAL, P0716
05-25	3L30(180C)	NO TCC APPLICATION
05-26	FORD	MASS AIR FLOW DIAGNOSIS
05-27	GM ALLISON 1000/2000	MODULATED LINE PRESSURE

**AUTOMATIC TRANSMISSION SERVICE GROUP**



## Technical Service Information

05-28	GM4L60-E	STACKEDSHIFTS 95-2000 "T" SERIESTRUCKS
05-29	ISUZU JR403E	ATFLEAKATAIR VENT
05-30	FORD	WHININGNOISEATBELLHOUSING
05-31	MITSUBISHI604	SCAN TOOLACCESS FORSNAP-ON
05-32	MAZDA/FORD	SCAN TOOLVEHICLE IDENTIFICATION
05-33	NISSAN RL4R01A	FALLSOUT OF 4th
05-34	FORD AX4S	OVERDRIVE BAND FAILURE
05-35	FORD 5R55W/S	NO 2nd OR 5th
05-36	GM 4T65E	TCC SURGEAND ORP0741