


WIRING DIAGRAM FOR SUSI ADAPTERS

MODEL # SWDGS5-SK, SWDGSR5-SK and SWDG435-SK

For SHARK METER IN SMALL GE CASE

WITH POWER CONNECTED

SERVICE: DELTA, 3-WIRE WITH 2 PTs AND 2 CTs



NOTES:

1. SELECT "2 Ct dEL" (2 CT DELTA) IN METER PROGRAMMING SETUP.
2. CONNECT GND DURING INSTALLATION AS DESIRED.

H	11/19/15	MS			Converted to Shark only
G	05/13/13	MS			Fixed font sizes and Spelling
F	12/11/12	MS			Updated Logo
E	4/29/09	CM			Added 2 Shorting circuiting bars
B	2/18/09	CM			Added 2 Current Jumpers
A	12/01/08	RH			INITIAL RELEASE
REV.	DATE	BY	CHK	APVD	REVISION DESCRIPTION
INFORMATION ON THIS DRAWING IS THE SOLE PROPERTY OF SUSI ADAPTERS. DO NOT COPY OR DISTRIBUTE WITHOUT WRITTEN PERMISSION FROM SUSI ADAPTERS. INTERPRET PER ANSI Y14.5 DO NOT SCALE DRAWING! ALL DIMENSIONS IN INCHES UNLESS NOTED OTHERWISE TOLERANCES SHALL BE: XXX = ± .005 X = ± .05 XX = ± .015 ANGLES: ± 0.5					
					SUSI ADAPTERS 9560 Red Bird Lane Johns Creek, GA 30022 PH: 770-448-6810 www.SUSIadapters.com
			DWN:	RLH	TITLE:
			DATE:	11/20/08	SWDGS5-SK & SWDGSR5-SK SHARK METER WIRING
			CHK:		DWG. NO. 610-1502-02
			ENGR:		REV: H
			SHEET	of 1	SCALE: 0.4" = 1" DWG SIZE: B