




Wiring Diagram for Schneider Electric ION 7400, PM 5000, & PM 8000 series meter in GE small Case with control power connected 2 Element, ESK & KYZ Optional

SUSI Adapters # SWDGS5-74, SWDGS5-5000, SWDGS5-8000



Back View

Notes:

1. Factory connected A phase voltage to the Control Power to power the meter electronics.
2. Connect "GND" as needed during installation
3. Fuses are recommended