


WIRING DIAGRAM FOR SUSI ADAPTERS MODEL # SWDGL9-SK & SWDGLR9-SK FOR SHARK METER IN GE CASE WITH POWER CONNECTED

SERVICE: WYE, 4-WIRE WITH 3 PTs AND 3 CTs



SIDE VIEW

NOTES:

1. SELECT "3 EL WYE" (3 ELEMENT WYE) IN METER PROGRAMMING SETUP.
2. CONNECT GND DURING INSTALLATION AS DESIRED.

F	08/16/2018	MS			Fixed GND
E	12/10/2012	MS			Updated New Logo
D	10/12/10	SB			Updated Mailing Address
C	2/18/09	CM			Changed L to N
B	12/01/08	RH			INITIAL RELEASE
REV	DATE	BY	CHK	APVD	REVISION DESCRIPTION

INFORMATION ON THIS DRAWING IS THE SOLE PROPERTY OF SUSI ADAPTERS. DO NOT COPY OR DISTRIBUTE WITHOUT WRITTEN PERMISSION FROM SUSI ADAPTERS.

INTERPRET PER ANSI Y14.5
DO NOT SCALE DRAWING!
ALL DIMENSIONS IN INCHES
UNLESS NOTED OTHERWISE
TOLERANCES SHALL BE:
XXX = ± .005 X = ± .05
XX = ± .015 ANGLES: ± 0.5



SUSI ADAPTERS
9560 RED BIRD LANE
JOHNS CREEK, GA 30022
PH: 770-448-6810 www.SUSIadapters.com

DWN: RLH	TITLE:
DATE: 11/20/08	SWDGL9-SK & SWDGLR9-SK SHARK METER WIRING
CHK:	DWG. NO. 610-1510-04
ENGR:	REV: F
SHEET 01 1	SCALE: 0.4" = 1" DWG SIZE: B