




Wiring Diagram for PM5500 Series meter in a Westinghouse FT-21 case (2 Element) with Power Supply Connected, SUSI Adapters # SWDWS5-PM55 & SWDWL5-PM55



Back View

Notes:

1. Connect "GND" as needed during installation
2. Fuses are recommended

610-1522-55-C