File Original and First Copy with Department of Ecology
Second Copy—Owner's Copy
Third Copy—Driller's Copy

WATER WELL REPORT

STATE OF WASHINGTON

Start Card No 056584

Water Right Permit No

1) **OWNER:** Name Doran-Johnson General Contractors Address W. 1503 Shannon, Spokane, WA 99205

LOCATION OF WELL: County Spokane SW ¼ NW ¼ Sec 3 T. 26 N., R 43 W.M.

(2a) **STREET ADDDRESS OF WELL** (or nearest address)

(3) **PROPOSED USE:** ☒ Domestic ☐ Industrial ☐ Municipal ☐ ☐ Irrigation ☐ Test Well ☐ Other ☐ ☐ DeWater

(4) **TYPE OF WORK:** Owner's number of well (if more than one)

Abandoned ☐ New well ☒ Method: Dug ☐ Bored ☐ Deepened ☐ Cable ☐ Driven ☐ Reconditioned ☐ Rotary ☐ Jetted ☐

(5) **DIMENSIONS:** Diameter of well 6 inches. Drilled 100 feet. Depth of completed well 100 ft.

(6) **CONSTRUCTION DETAILS:**

Casing installed: 6 " Diam. from +2 ft. to 73 ft.
Welded ☒ PVC 4 " Diam. from 8 ft. to 100 ft.
Liner installed ☒
Threaded ☐ " Diam. from ft. to ft.

Perforations: Yes ☒ No ☐ PVC Liner
Type of perforator used Skill Saw
SIZE of perforations 1/4 in. by 12 in.
15 perforations from 100 ft. to 80 ft.
perforations from ft. to ft.
perforations from ft. to ft.

Screens: Yes ☐ No ☒
Manufacturer's Name
Type Model No
Diam. Slot size from ft. to ft.
Diam. Slot size from ft. to ft.

Gravel packed: Yes ☐ No ☒ Size of gravel
Gravel placed from ft. to ft.

Surface seal: Yes ☒ No ☐ To what depth? 18 ft.
Material used in seal Bentonite Slurry
Did any strata contain unusable water? Yes ☒ No ☐
Type of water? Surface Depth of strata 32'
Method of sealing strata off Casing

(7) **PUMP:** Manufacturer's Name
Type: H.P

(8) **WATER LEVELS:** Land-surface elevation above mean sea level ft.
Static level 75 ft. below top of well Date July 3, 1991
Artesian pressure lbs. per square inch Date
Artesian water is controlled by (Cap, valve, etc.)

(9) **WELL TESTS:** Drawdown is amount water level is lowered below static level
Was a pump test made? Yes ☐ No ☒ If yes, by whom?
Yield: 80 gal./min. with ft. drawdown after hrs.
" " " " " "
" ESTIMATED AIRLIFT " " " "

Recovery data (time taken as zero when pump turned off) (water level measured from well top to water level)

Time	Water Level	Time	Water Level	Time	Water Level

Date of test

Bailer test gal./min. with ft. drawdown after hrs.
Airtest gal./min. with stem set at ft. for hrs.
Artesian flow g.p.m. Date
Temperature of water Was a chemical analysis made? Yes ☐ No ☐

(10) **WELL LOG or ABANDONMENT PROCEDURE DESCRIPTION**

Formation: Describe by color, character, size of material and structure, and show thickness of aquifers and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of information.

MATERIAL	FROM	TO
Top soil	0	1
Sand, Fine, W/Silt	1	8
Cobble and Gravel	8	10
Sand and Gravel	10	18
Sand and Gravel, Water Bearing	18	32
Clay, Light Grey	32	38
Sand and Gravel	38	40
Clay, Light Brown, Some Sand, Fine	40	63
Sand, Gravel, W/Clay, Water Bearing	63	73
Basalt, Black, Medium	73	95
Basalt, Fractured, Black	95	100
6" Drive Shoe Utilized		

RECEIVED JUL 2

Work started 7-2 19 91 completed 7-3 19 91

WELL CONSTRUCTOR CERTIFICATION:

I constructed and/or accept responsibility for construction of this well, and its compliance with all Washington well construction standards. Materials used and the information reported above are true to my best knowledge and belief.

NAME Ponderosa Drilling & Development, Inc. (PERSON, FIRM, OR CORPORATION) (TYPE OR PRINT)

Address E. 6010 Broadway, Spokane, WA 99212

(Signed) Martin Jensen (WELL DRILLER) License No. 1933

Contractor's Registration No. PO-ND-EI248JE (Martin Jensen) Date July 5 19 91

(USE ADDITIONAL SHEETS IF NECESSARY)

ECY 050-1-20 (10/87) -1329-

The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.