



INSPECTION REPORT

DATE: 7/16/25

CUSTOMER: Keith Johnson

ADDRESS: 4057 Jewel Lake Rd.

TANK SIZE: unknown 8-1000

INSPECTION REPORT: p/o septic tank. Tank is
a metal drum (oldschool) condition unknown
Tank plus drainfield appear to work well so far.

INSPECTED BY: CASEY MCMASTER

SUCCESS SEPTIC PUMPING is not liable for any current or future septic issues related to this inspection. All statements made in this inspection are true and accurate to the best of my knowledge at the time of the inspection.