



Foto Nr. 37: WE Nr. 3, 1. OG links, Terrasse



Foto Nr. 38: WE Nr. 3, 1. OG links, Wohnzimmer



Foto Nr. 39: WE Nr. 3, 1. OG links, Bad



Foto Nr. 40: WE Nr. 3, 1. OG links, WC



Foto Nr. 41: WE Nr. 4, 1. OG hinten links, Eingang



Foto Nr. 42: WE Nr. 5, 2. OG rechts, Eingangsbereich





Foto Nr. 43: WE Nr. 5, 2. OG rechts, Bad



Foto Nr. 44: WE Nr. 5, 2. OG rechts, Wohnzimmer



Foto Nr. 45: WE Nr. 5, 2. OG rechts, Balkon



Foto Nr. 46: WE Nr. 5, 2. OG rechts, Küche




Foto Nr. 47: Laubengang / Außentreppe



Foto Nr. 48: WE Nr. 6, 2. OG mittig, Diele / Küche





Foto Nr. 49: WE Nr. 6, 2. OG mittig, Küche



Foto Nr. 50: WE Nr. 6, 2. OG mittig, Balkon



Foto Nr. 51: WE Nr. 6, 2. OG mittig, Wohnzimmer



Foto Nr. 52: WE Nr. 6, 2. OG mittig, Bad





Foto Nr. 53: WE Nr. 6, 2. OG mittig, Bad



Foto Nr. 54: WE Nr. 7, 2. OG links, Eingang



Foto Nr. 55: WE Nr. 8, 2. OG hinten links, Diele




Foto Nr. 56: WE Nr. 8, 2. OG hinten links, Küche



Foto Nr. 57: WE Nr. 8, 2. OG hinten links, Wohnzimmer



Foto Nr. 58: WE Nr. 8, 2. OG hinten links, Balkon





Foto Nr. 59: WE Nr. 8, 2. OG hinten links, Bad



Foto Nr. 60: WE Nr. 9, 3. OG rechts, Diele



Foto Nr. 61: WE Nr. 9, 3. OG rechts, Küche



Foto Nr. 62: WE Nr. 9, 3. OG rechts, Wohnzimmer



Foto Nr. 63: WE Nr. 9, 3. OG rechts, Balkon



Foto Nr. 64: WE Nr. 9, 3. OG rechts, Kinderzimmer





Foto Nr. 65: WE Nr. 9, 3. OG rechts, Bad



Foto Nr.66: WE Nr. 9, 3. OG rechts, Schlafzimmer



Foto Nr. 67: WE Nr. 10, 3. OG mittig, Diele



Foto Nr. 68: WE Nr. 10, 3. OG mittig, Küche



Foto Nr. 69: WE Nr. 10, 3. OG mittig, Balkon



Foto Nr. 70: WE Nr. 10, 3. OG mittig, Schlafzimmer





Foto Nr. 71: WE Nr. 10, 3. OG mittig, Bad



Foto Nr. 72: WE Nr. 11, 3. OG links, Eingang



Foto Nr. 73: Außentreppe



Foto Nr. 74: WE Nr. 12, 3. OG hinten links, Diele



Foto Nr. 75: WE Nr. 12, 3. OG hinten links, Küche



Foto Nr. 76: WE Nr. 12, 3. OG hinten links, Wohnzimmer





Foto Nr. 77: WE Nr. 12, 3. OG hinten links, Bad



Foto Nr. 78: WE Nr. 12, 3. OG hinten links, WC



Foto Nr. 79: WE Nr. 13, 4. OG rechts, Schlafzimmer - Foto vom 10.02.2022



Foto Nr. 80: WE Nr. 13, 4. OG rechts, Diele - Foto vom 10.02.2022



Foto Nr. 81: WE Nr. 13, 4. OG rechts, Badezimmer - Foto vom 10.02.2022



Foto Nr. 82: WE Nr. 13, 4. OG rechts, Badezimmer - Foto vom 10.02.2022





Foto Nr. 83: WE Nr. 13, 4. OG rechts, Kinderzimmer - Foto vom 10.02.2022



Foto Nr. 84: WE Nr. 14, 4. OG mittig, Eingang



Foto Nr. 85: Flachdach über dem Erdgeschoss




Foto Nr. 86: WE Nr. 15, 4. OG links, Diele - Foto vom 10.02.2022